



After grit blasting, leaks repaired with DurAlloy.



DuraWrap Primer applied.

Client: Waste water treatment plant.
Location: Northeastern U.S.
Problem: Corroded & leaking main influent pipe.
Solution: Repair leaks with *DurAlloy*; reclaim pipe with *DuraWrap Carbon Fiber Pipe Wrap System*.
Cost: \$40,000 total turn-key project.
Savings: \$100,000+ replacement cost.



DuraWrap Carbon Fiber, impregnated with DuraWrap Polymers, being wrapped around pipe section.



Completed DuraWrap System.

6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com