

Oil Company in Thailand Repairs 22 'Problem Areas' with DuraWrap



Client: Major oil company

Location: Thailand

Problem: 20" diameter pipe was severely rusting in 22 different locations.

Solution: Original galvanized coating was removed. Rusted areas were manually prepared by grinding and wire brushing. *DurAlloy* was used to repair any damaged areas on the pipe. *DuraWrap Primer* was applied followed by two layers of *DuraWrap Carbon Fiber System*.



Before



After



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com