



ENECON Italia Solves Cavitation Problems For Ferry Boat Operator

*Cavitation problems
on a ferryboat's
salt-water discharger
repaired and protected
from future attack with
DuraTough DP & DL*

Severe cavitation damage clearly evident on discharger after grit blasting/cleaning.

DuraTough Primer applied to the prepared surface.



DuraTough DP applied to re-build damaged surface.



DuraTough DL applied to completely seal and protect the discharger.