

ENEFLOW Solves Mineral Scale Problem at Major Bottling Plant in Venezuela

A large brewery and bottling plant in Venezuela was having problems with mineral scale build-up in their bottle washing machinery. The machines would have to be shut down constantly for cleaning due to the severe scaling issues.

SUDICA, ENECON's distributor in Venezuela, convinced the customer to conduct an ENEFLOW trial. They agreed to a 30 day test of two installations – one pair of ENEFLOW 5000's on the 3" raw water feed line, and 2 pairs of ENFLOW 1000's on a 5" suction pump line.

The trial was to be monitored every couple of days to determine the results.

The improvement was noticeable within days. ENEFLOW stopped the scale formation completely! An internal report issued by the customer indicates the machines are now able to run without interruption, increasing weekly output by thousands of units!



That's the ENEFLOW Effect...

- **Stop Mineral Scale Build-Up**
- **Improve Efficiency**
- **Save \$\$\$!!!**



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com