



Tugboat Operator Selects CeramAlloy to Combat Erosion/Corrosion on Their Kort Nozzles



This tugboat belonging to a major international marine company in Florida was suffering from the effects of erosion & corrosion on its Kort nozzles. The local ENECON Fluid Flow Systems Specialist was called in to help find a solution.

After preparing the surface by grit blasting to acquire a 'white metal' finish, two coats of CeramAlloy CL+AC were applied.

The owner of the vessel was so pleased with the final results that another tugboat's Kort nozzles have already been scheduled for repair.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON® (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com