



At this chemical storage area in a large Boston hotel's laundry, chemical corrosion had severely damaged the diamond plate platforms.

The hotel engineers are delighted with the results and the cost savings over traditional repair or replacement procedures.

The hotel's facilities engineer wanted a more durable as well as cost effective solution to their usual paint or replace procedures.

### CHEMCLAD SC...

- Cost Effective!
- Easy to Use!
- Solvent Free!
- Highly Durable!



He turned to ENECON North East for some guidance. The local ENECON Fluid Flow Systems Specialist suggested grit blasting the diamond plate and then applying two coats of **CHEMCLAD SC.**

**Excellent Chemical Resistance!**

