

Spanish Nuclear Power Plant Repairs & Protects Cooling Water Storage Pools with DuraQuartz, DuraFill & CHEMCLAD SC





These massive concrete storage pools at a major nuclear power station in Spain needed to be repaired and protected.

The plant engineers selected ENECON's high performance repair composites (**DuraQuartz** and **DuraFill**) to repair any damaged concrete

and to screed and prime all the concrete surfaces of the pools, thus insuring a very smooth and crack-free surface.

One coat of **CHEMCLAD SC** was then applied over the entire pool area in order to provide a water-proof and maintenance-free surface.

This prestigious **\$1.5 MILLION** project, which also included two cooling tower pools and associated channels, was completed on time and within budget by ENECON Ibérica to the complete satisfaction of the plant engineers.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com