

## European Refinery Repairs & Protects Cooling Water Pumps With CeramAlloy

At this major refinery located near Antwerp, Belgium, erosion and corrosion problems were a constant maintenance issue for the plant's engineers. A number of years ago, they decided to repair and protect their cooling water pumps with

CeramAlloy CP+AC and CL+AC.

The maintenance engineers have been delighted with the results and this series of photos illustrates a typical cooling water pump repair procedure.



700 Hicksville Road • ENECON Center Suite 110 • Bethpage, NY 11714  
Toll Free: 888-4-ENECON • Phone: 516.349.0022 • Fax: 516.349.5522  
[www.enecon.com](http://www.enecon.com) • [info@enecon.com](mailto:info@enecon.com)