



Polish Research Laboratory Protects Heavy Traffic Area Floors with ENECRETE & ENECLAD

The floors at this Polish research laboratory were subjected to material transport carts that can exert forces on the floor of up to 10 tons per square meter.

The floors were failing creating an unsafe environment. ENECON Poland was contacted to help find a solution on over 6,000 sq. ft. of floor area.

The floors were first ground and all damaged areas were repaired with ENECRETE DuraFill with a locally sourced aggregate. DuraFill with two liberal broadcasts of a blue aggregate was then applied. Finally 3 coats of ENECLAD CFS were applied on top of the aggregate in order to create a highly durable, smooth finish.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com