



## ENECON Poland Repairs & Protects Critical Floor Area at Major Pharmaceutical Company with ENECLAD FPS-2000 & DuraQuartz

This international pharmaceutical company wanted a long-term solution to their flooring problems. They had tried a variety of other products with less than desirable results. The heavy steel-wheeled carts used at the plant destroyed conventional coating systems almost as soon as these were installed. They needed an "extraordinary floor protection product" and an "extraordinary company" that would work over a New Year's Holiday.

ENECON Poland was able to satisfy both requirements.

Working over New Year's Eve, all damaged areas to the concrete floor surfaces were repaired and rebuilt with ENECRETE DuraQuartz. Then two coats (red + gray) of FPS-2000 were applied to protect the entire floor area, providing a seamless and hygienic surface.

The plant engineers were very pleased with the final results and the on-going performance of the FPS system.



Damaged Concrete



DuraQuartz Repairs

